



Linksgewinde markiert mit L...

Part No.	Dimensions mm															
	d	d3	^{6H}	B	C1	L3 min	W	d2	d1	h1	L4	L5	d4	d5	dk	a ≈
PHS 4	4	M4x0.7	7	5,25	8	8	8	14	6,5	24	31	4	8	10	9,525	13
PHS 5	5	M5x0.8	8	6	10	9	9	16	7,7	27	35	4	8,5	11	11,11	13
PHS 6	6	M6x1.0	9	6,75	12	11	11	18	8,96	30	39	5	10	13	12,7	13
PHS 8	8	M8x1.25	12	9	16	14	14	22	10,4	36	47	5	12,5	16	15,875	14
PHS 10	10	M10x1.5	14	10,5	20	17	17	26	12,9	43	56	6,5	15	19	19,05	13
PHS 10-1	10	M10x1.25	14	10,5	20	17	17	26	12,9	43	56	6,5	15	19	19,05	13
www.mybearing.eu																
PHS 12	12	M12x1.75	16	12	22	19	19	30	15,4	50	65	6,5	17,5	22	22,225	13
PHS 12-1	12	M12x1.25	16	12	22	19	19	30	15,4	50	65	6,5	17,5	22	22,225	13
PHS 14	14	M14x2.0	19	13,5	25	22	22	34	16,9	57	74	8	20	25	25,4	16
PHS 14-1	14	M14x1.5	19	13,5	25	22	22	34	16,9	57	74	8	20	25	25,4	16
PHS 16	16	M16x2.0	21	15	28	22	22	40	19,4	64	84	8	22	27	28,575	15
PHS 16-1	16	M16x1.5	21	15	28	22	22	40	19,4	64	84	8	22	27	28,575	15
PHS 18	18	M18x1.5	23	16,5	32	27	27	44	21,9	71	93	10	25	31	31,75	15
PHS 20	20	M20x1.5	25	18	33	30	30	50	24,4	77	102	10	27,5	34	34,925	14
PHS 22	22	M22x1.5	28	20	37	32	32	54	25,8	84	111	12	30	38	38,1	15
PHS 25	25	M24x2.0	31	22	42	36	36	60	29,6	94	124	12	33,5	42	42,86	15
PHS 28	28	M27x2.0	35	24	48	41	41	66	32,3	103	136	14	37	46	47,63	15
PHS 30	30	M30x2.0	37	25	51	41	41	70	34,8	110	145	15	40	50	50,8	17
PHS 30-1	30	M27x2.0	37	25	51	41	41	70	34,8	110	145	15	40	50	50,8	17